

SAN MARTIN BLVD OVER RIVIERA BAY PD&E STUDY

EXISTING CONDITIONS



Functionally Obsolete

- Substandard Narrow Roadway Width
 - » 24.5 ft Wide - Curb to Curb
 - » Narrow Shoulders (<2 ft Wide)
 - » No Bike Lanes
- Substandard Sidewalks (<2 ft Wide)
 - » Do not Meet Requirements of the Americans with Disabilities Act (ADA) of 1990
- Substandard Bridge Railings and Guardrail

