




# Beckett Bridge PD&E Study




Historic Whitcomb Bayou Circa 1921



## Rehabilitation Alternative (No Widening)



- Repair deteriorated concrete deck underside and provide cathodic (corrosion) protection
- Repair deteriorated concrete of pile bent caps and provide cathodic (corrosion) protection



- Replace electrical systems and machinery



- Install crutch bents at Bents 2, 3, 4, 5, 9, 10
- Install new cathodic (corrosion) protection jackets on all concrete bent piles